

**COUNTY OF LOS ANGELES
OCEAN WATER MONITORING DATA**

Fresh Water Swim Areas

SAMPLE DATE: JUNE 5, 2016

REPORT DATE: JUNE 6, 2016

SS1- SEASIDE LAGOON REDONDO BEACH South end at equipment room	
SS2- SEASIDE LAGOON REDONDO BEACH West end at slides	
SS3- SEASIDE LAGOON REDONDO BEACH North end at lifeguard tower	
SS4- SEASIDE LAGOON REDONDO BEACH South end at fountain	
SS5- PYRAMID LAKE VAQUERO BEACH North swim area	
SS6- PYRAMID LAKE VAQUERO BEACH South swim area	
SS7- PYRAMID LAKE IMMIGRANTS LANDING North swim area	
SS8- PYRAMID LAKE IMMIGRANTS LANDING South swim area	
SS9- CASTAIC LAKE South Swim Area At Lifeguard Tower	
SS10- CASTAIC LAKE North Swim Area South end of swim area	
SS11- CASTAIC LAKE North of Lifeguard Tower North end of swim area	
SS11B- CASTAIC LAKE North of Lifeguard Tower Middle of swim area	

SS12- SANTA FE DAM FRONT OF LIFEGUARD TOWER 1	
SS13- SANTA FE DAM FRONT OF LIFEGUARD TOWER 2	
SS14- SANTA FE DAM FRONT OF LIFEGUARD TOWER 3	
SS15- SANTA FE DAM FRONT OF LIFEGUARD TOWER 4	
SS16- SANTA FE DAM FRONT OF LIFEGUARD TOWER 5	
SS17- BONELLI PARK SOUTH LIFEGUARD TOWER	
SS18- BONELLI PARK MIDDLE LIFEGUARD TOWER	
SS19- BONELLI PARK NORTH LIFEGUARD TOWER	

A Check Mark indicates that the sampling site met State bacteriological standards.

A Slash Symbol indicates that the sampling site did not meet State bacteriological standards.

Seaside Lagoon, Castaic Lake, Santa Fe Dam, and Bonelli Park are equipped with chlorination systems.